

~~CONFIDENTIAL RESTRICTED~~ 130

WAR DEPARTMENT

U. S. ARMY AIR FORCES

REPORT OF AIRCRAFT ACCIDENT

44-4-24-523

(1) Place Grafton Underwood (2) Date 24 April, 1944 (3) Time 1407

AIRCRAFT: (4) Type and model B-17-G 070 (5) A. F. No. 2-37789 (6) Station 106

Organization: (7) 8th Air Force (8) 384 Bomb (H) (9) 544 Bombardment (H)

(Command and Air Force) (Group) (Squadron)

PERSONNEL BH

2354

DUTY (10)	NAME (Last name first) (11)	RATING (12)	SERIAL NO. (13)	RANK (14)	PERSONNEL CLASS (15)	BRANCH (16)	AIR FORCE OR COMMAND (17)	RESULT TO PERSONNEL (18)	USE OF PARACHUTE (19)
0/P Nuttall, Alfred C.	P 0-404094 Lt. Col.	1801		O1	AC	8th AF	None	None	
4/C Cole, Alfred H.	P 0-692763 2nd Lt.	1801		O1	AC	8th AF	None	None	
6/N Gantert, Harold F.	N 0-703977 2nd Lt.	1801		O1	AC	8th AF	None	None	
1/R Anderson, Charles L.	RO 1616876 T/Sgt.	3820		O1	AC	8th AF	None	None	

RECEIVED

1-7-44

10

PILOT CHARGED WITH ACCIDENT

(20) Nuttall, Alfred C. (21) 0-404094 (22) Lt. Col. (23) 18 (24) AC
(Last name) (First name) (Middle initial) (Serial number) (Rank) (Personal class) (Branch)Assigned (25) 8th Air Force (26) 384 Bomb (H) (27) 544 Bombardment (H) (28) 106
(Command and Air Force) (Group) (Squadron) (Station)Attached for flying (29) 8th Air Force (30) 384 Bomb (H) (31) 544 Bombardment (H) (32) 106
(Command and Air Force) (Group) (Squadron) (Station) 2354Original rating (33) Pilot (34) 7-7-41 Present rating (35) Pilot (36) 7-7-41 Instrument rating (37) 12 March, 1943
(Rating) (Date) (Rating) (Date) (Date)

FIRST PILOT HOURS:

(at the time of this accident)

(38) This type	966:35	(42) Instrument time last 6 months	00:00
(39) This model	73:00	(43) Instrument time last 30 days	00:00
(40) Last 90 days	64:20	(44) Night time last 6 months	01:30
(41) Total	1726:30	(45) Night time last 30 days	00:00

AIRCRAFT DAMAGE NF

DAMAGE	(46) LIST OF DAMAGED PARTS			
(46) Aircraft	5	"W'S	"O"4	Salvaged
(47) Engine(s)	"W'S	"W'S	"O"4	Complete destruction to aircraft except, right outer wing, #2 & 3 drops & engines, tail.
(48) Propeller(s)	"W'S	"W'S	"O"4	

(50) Weather at the time of accident Ceiling 5/10 at 2,500 feet, 10/10th over 10,000 feet visibility seven (7) miles. Surface wind West at sixteen miles per hour.

(51) Was the pilot flying on instruments at the time of accident NO

(52) Cleared from 106 (53) To Local Flying (54) Kind of clearance Contact

(55) Pilot's mission Training

(56) Nature of accident Left wing fire

(57) Cause of accident Gasoline was syphoning from left wing, caught on fire and exploded while aircraft was twenty (20) feet above landing end of runway.

REF ID: A814

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

In the Opinion of this board the accident was due to one hundred (100%) percent mechanical failure.

Due to the fact the aircraft was two thirds demolished by fire actual mechanical failure is unknown.

Lieutenant Colonel Nuttall noticed, immediately after take-off, gasoline was syphoning from number one (1) engine. Rocking of wings violently failed to stop flow of gasoline.

Lieutenant Colonel Nuttall's next intention was to land immediately. He was cleared by tower as number one (1) to land, and while on final approach, approximately twenty (20) feet above landing end of runway, the left outer wing blew up. The impact of the aircraft "Dropping in" from approximately twenty (20) feet caused the left landing gear to collapse, throwing aircraft to left of runway, where it was two thirds demolished by fire.

Signature

Thomas P. Beckett
(Investigating Officer)

Thomas P. Beckett, Lt. Col., AC

Arthur M. Stone Jr.
Arthur M. Stone Jr., CHOT, AC

Charles W. Bishop
Charles W. Bishop, 1st Lt., AC

544TH BOMBARDMENT SQUADRON (H) AAF
Office of the Squadron Commander

24 April 1944

SUBJECT: Statement of Accident of B-17G A/C #42-37789.

TO : Commanding Officer, Station 106, APO 557.

1. I took off on a practice and test flight at 1400 on 24 April 1944. Immediately after take-off I noticed that gasoline was coming from #1 engine. I then decided to land immediately. I tried rocking the wings violently to stop the flow but to no avail. On the final approach just as the plane was about to cross the end of the runway, the fuel caught fire. At about 20 ft in the air the wing exploded and the wing from #1 engine out was blown off. The ship fell off to the left and hit the runway very hard which caused the left landing gear to collapse. Engines were cut immediately and we came to a stop. The Co-Pilot left the plane through the right cockpit window and the rest of the crew through the main entrance way. No injuries were sustained. Landed at 1407.

Alfred C. Nuttall
ALFRED C. NUTTALL,
Lt Col., Air Corps,
Commanding Officer.

HEADQUARTERS
REF ID: AAF STATION NO. 106
Office of the Flying Control Officer

R-2-5

April 24, 1944.

SUBJECT: Crash Landing of B-17 #7789.

TO : COMMANDING OFFICER, AAF Station No. 106.

1. At 1400 hours 7789 took off on a local high altitude flight. Immediately after becoming airborne the pilot called for landing instructions. He was cleared for immediate landing.

2. Just before touching down I noticed fire coming from the port wing. As the aircraft touched down the left wheel collapsed and flames burst from the left side of the aircraft. The aircraft swerved off the runway to the left.

3. Upon seeing the plane crash land I immediately dispatched the crash trucks, ambulance and notified all concerned.

J. H. Burgholder
J. H. BURGHOLDER,
1st Lt., Air Corps,
Flying Control Officer.

RESTRICTED



(GAD 55-4-334)(24-4-#7)(AC-12-37789)(8-17-8)



(010-65-2-386) 244-44 X AC-#2-37789 (0-17)