ACCIDENT No.

U. S. ARMY AIR FORCES

REPORT OF AIRCRAFT ACCIDENT 45-4-25-702

monage: (A) Type and model B=170	1	(5) A. I	No. 43-	39138	6) Station	106	Time51	<b>5</b>
Organization: (7) Eight!	A bas bas		(Group) ERSONNEL*	ED. (H M) -		(Squada	rom)	
	1	1		PERSONNEL			1 200	Use or
TI (Last name first)	RATING	SERIAL NO.	RANK	CLASS	BRANCE	AIR FORCE OR COMMAND	PRESULT TO PRESONNEL	PARACHT
7 (11)	(19)	0 780790	(14)	18	(16)	8th AF	(18) N13	(19) N1
P Hober, Merrill Da	P	0-780580 0-832101	let It	18	AC AC	8th AF	Hil	N1
Hemilton, Frederick Ke	N	0-2071406		18	AC	8th AF	Mil	Mi
Brubsker, James No.		18226876	3/3et	38	AC	8th AF	NAL	. Y1
Wininger, Dexter De		15364135	T/Sgt	36	AC	8th AF	Nil	Bi
Fulmer, LeRoy Be		15076562	1/3gt	38	AC	8th AF	Nil	
Marrita, Raymond A.		38535947	S/Set	38	C	8th AF	Wil Wil	Ni Ni
Clements, William H.		.38510297 .36802883	S/Sgt.	38	AC	8th AF	Wil	W1
Plant, George Ja		JUMESHIJ.				××××		
			š.				•	
1								
er Pilor Houns: the time of this accident)  30) This type		207.8	5 (43) 25 (44)	Instrument	time last 6 z	nonths days		8 20
		AIRC	BAJT DAMA			6,75 kg		
DAMAGE			-			lago dame	ed here	-d
Aircraft Wil Wil	Mil		dr		QL. AMPE	MAKE	CAT DATA	
	Hil	Wil						14.
Weather at the time of accident	at the t	ime of accident	No.	per him	<u> </u>	olearance .Op		
) PRot's mission Operational  Nature of accident Landing ac	older	t. pilot 1	ost cont	ol after	landin	g and gro	and loop	ed
into another sircreft par	lad.a	n field.						
7) Cause of accidentRight. brak (8) Hes. for#54 been submit				mga.to.)		S. Lines.		······································
Incl #	7	24	STRUCTE					

### RESTRICTED WAR DEPARTMENT

U. S. ARMY AIR FORCES

Accident No.

Turglanes

### REPORT OF AIRCRAFT ACCIDENT

25 April, 1945 (1) Place PAAF STATION 106. AIRCRAFT: (4) Type and model B-170 (5) A. F. No. 43-39138 (6) Station 106 Organization: (7) Eighth Air Force (8), 384th Bomb (H) 544th Bomb (H) PERSONNEL AIR FORCE OR COMMAND PERSONNEL CLASS RESULT TO PERSONNEL USE OF PARACHUTE SERIAL NO. RANK BRANCH DUTY RATING (15) (16) (17) (18) (19)(12) (14)(13) (10) (11) 0-780580 1st Lt AC 8th AF Nil Nil P P Grove Alfred W. 0-832404 18 AC 8th AF Nil Nil P 2nd Lt CP Hoban, Merrill D. 0-2071406 2nd Lt 18 AC 8th AF Nil Nil N N Hamilton, Frederick K. S/Sgt T/Sgt 38 AC 8th AF Nil Nil 18226876 T Brubaker, James Me. 8th AF Wininger, Dexter D. Nil 15364135 38 AC Nil T/Sgt 8th AF Nil Nil 15076562 38 AC TT Fulmer, LeRoy E. 38535947 S/Sgt 38. AC 8th AF Nil Nil BT Marwitz, Raymond A. 8th AF Nil Nil TG Clements, William H. 38510297 S/Set 38 AC 8th AF Nil Nil 36802883 F Plont, George J. (21) 0-780580 (Serial number) (22) 1st Lt (23) 18 (Personnel Alfred (Middle initial) Grove Assigned (25) Eighth Air Force (26) 384th Bomb (H) 544th Bomb (H) (28) (Group) Attached for flying (29) (Command and Air Force) (Group) (31) Original rating (33) Pilot. (34) 27/6/11. Present rating (35) Pilot. (36) 27/6/11. Instrument rating (37) 27/6/11. (Date) FIRST PILOT HOURS: (at the time of this accident) (38) This type..... 349:05 (42) Instrument time last 6 months..... (39) This model..... 287 :45 (43) Instrument time last 30 days..... ...251.125 (44) Night time last 6 months..... (40) Last 90 days\_\_\_\_\_ 349 205 ... (45) Night time last 30 days..... (41) Total..... AIRCRAFT DAMAGE DAMAGE (49) LIST OF DAMAGED PARTS Entire forward part of fuselage damaged beyond (46) Aircraft. Nil Nil Nil Nil. repair. (47) Engine(s) .... Nil Nil (48) Propeller(s)... (50) Weather at the time of accident 8/10ths clouds, base three thousand (3,000) feet, visibility seven (7) miles, wind Southwest eight (8) miles per hour. (51) Was the pilot flying on instruments at the time of accident No. (52) Cleared from Station 106 (53) To Operational (55) Pilot's mission Operational (56) Nature of accident Landing accident, pilot lost control after landing and ground looped into another aircraft parked on field. (57) Cause of accident Right brake failed due to flak damage to hydraulic lines. (58) Has form5h been submitted? No.

RESTRICTED

Incl #7



(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

The aircraft had sustained considerable flak damage over the target, and was returning alone on three (3) engines. The damage included a broken hydraulic line between the right brake pedal and the brake itself. This line is not under pressure until the brake pedal is depressed. Upon reaching the English Coast, the pilot made a routine check of the hydraulic system by noting the pressure gauge and by operating the cowl flaps (also hydraulically operated). Everything seemed normal to him but he had failed to check the broken line, which could have been done by depressing the brake pedals. Upon landing and applying brakes, the left brake held but the right brake was ineffective. Furthermore the accumulated pressure, being only then exposed to the severed line immediately collapsed. Of course, the left brake swerved the plane to the left, off the runway, starting a ground loop. The left engines were used a little too late in trying to straighten out, and were relatively ineffective. The ground loop was almost complete when Lieutenant Grove's aircraft struck another aircraft parked about four hundred (400) feet from the landing runway.

The accident could have been avoided if the pilot had known that the right brake was out. And he would have known that if he had made the proper check in the air. However, this pilot states that, in training, he was told not to check the brakes in that manner and since then it had not been his policy to do so. Two (2) members of this board know of the existence of such instructions in some training stations in the United States. Heretofore it has not been this station's policy to warn pilots about the above mentioned check &

Immediate Cause: Uncontrolled ground loop after landing.

Underlying Cause: Right brake out, (unknown to pilot) due to enemy action.

Responsibility: Fifty (50) percent pilot error

Fifty (50) percent supervisory personnel

Recommendations: That all pilots flying B-17 type aircraft on operational missions be instructed to always check brakes, by depressing brake pedal prior to landing.

Aircraft Accident Committee: Philip Y. Williams, Major, Air Corps, Pilot - President

> Clarence L. THACKER, Major, Air Corps, Pilot - Member

OLAI (NMI) HANSEN, Major, Air Corps, Engineering Officer - Member.

Gulliam Kernby WILLIAM R. CROSBY, Capt, Air Corps, Flight Surgeon (ex-officio)

let It, Air Corps, Intelligence Officer (ex-officio)

Signature	(Investigating Officer)
	***************************************

Date 1 May 1945.

Hq 505 USAPP/8-43/25M/13350 RESTRICTED

April 25, 1945 106			GROUP N	GROUP NO. & TYPE 384th					AIRCRAFT MODEL B-17G				
	s/Sgt ChristyMante		SQUADRO	SQUADRON No. & TYPE					AIRCRAFT SERIAL No. 43-39138				
PERS. CLASS		USE AS DIRECTED LOCALLY	ALWAYS ENTER DUTY S CABLE, ENTER N-NIGH ENTER TIME FLOV			FLOW	VN THERELINDER		NT.	FLIGHT DATA			
1		2	3	DUTY NORT D		I DUTY	NORL	6 OUTY NOR	DUTY	N OR I	TERMINALS AT	ND MISSION	9
18	Grove, Alfred	We lst Lt 0=780580	544	P 9	: 05			:			FROM:		05:
18	Hoban, Merrill	L D. 2nd Lt 0-832404	n	CP 9	: 05					*******	TO: COME	TA	IIi:
18	Hamilton, Free	lrick R. 2nd Lt 0-2074406		N 9	05						MISSIONS	NO. OF LANDINGS	09:
38	Fulmer, LeRoy	E. T/Sgt 15076562	10	9							FROM		G
38	Wininger, Dext	er G. T/Sgt 15364135		RO 9				:			TO:	*********	I.
38	Brubaker, Jame	s N. S/Sgt 18226876		TOG	05						MISSION	NO, OF	:
38	Clements, Will	iam H. S/Sgt 38570297		9 :		-					FROM:		1
38	Marwitz, Raymo	nd & S/Sgt 38535947	**	G 9 :	05	:					то:	******	:
38	Plent, George		546	F 9:		:					MISSION:	NO, OF LANDENUS	
						!					FROM:		0
										*****	то		
	A TRUE EX	TRACT COPY:						1			MISSION:	NO. OF LANDINGS	0
	Mel.	Mal									FROM:		:
	WILLIAM T	J. Shoran		:				:			To:	********	:
	Major, Ai			!							MISSION:	NO. OF LANDINGS	:
WAR DEP A. A. F. F. REV. (1 J	PARTMENT ORM No. 1 AN. 44)	AIRPLANE FLIGHT REPORT	- OPERATION	s	ī	CHECK	AND	OPER.	TRAN TOTAL TIME E ON FO	FLIGH	ED CREW	TOTAL FLIGHT TIME	09

WAR DEFAR MINERS A. A. F. FORM NO. 1 A REV. (1 JAN. 461)

### AIR ANE FLIGHT REPORT - ENG NE RING

		INSP	ECTION STATUS		9 "	K1 74	200	SERV	CK IMM		ATION	200.00	COLOR SPACE IN			
		E OF	INSPE	CTED TODAY		FU	EL			-	0	-				80
		UE	ву	STATION	SERVICE		ONS)				(QUA					RADIATOR
PREFLIGHT	25-	4-45	M		ER	M BERV.	V- IN	NO. 1		NO. 2		NO. 3		NO. 4		NEC H
DAILY	25-	4-45	M		0	ICED	TANKS		TANKS	SERV-	TANKS	SERV-	TANKS	SERV-	IN	20
25 HOURS		:20			157		2700		110		110		10		110	
50 HOURS	483	:20		106	210											
100 HOURS	533	:20			3RD											
S.P.	458	:20			4TH											
Batt		M			STH											
	INSPE	CTION O	F AUXILIARY EQ	UIPMENT		STATUS										
EQUIPMEN	T	SYMBOL	INSPECTED BY	STATION		TODAY	2.	XPLA	NATIO	4:						
BOMBARDME	NT	J.	Cohen	106	1	, )	X									
GUNNERY					3	and the same of the same	4.									
Radar		P	Parry	106												
COMMUNICA	TIONS	W	Wilmes	106	EXCEPTIONAL RELEASE											
PHOTOGRAPI	HIC				1	AND .	THE E	XCEPT	IONAL.	RELE	ASE .	HAS !	OT B	EEN G	RANTE	D
Gee MAXXXXXXXX		Н	Hugerien				AFT W								OF TH	E
							SED F	DR	11-				3			
									1.2.				4		-	

O2 OK-Aptil lt
Flight #1 Upper Turret Operates only part of the time,
Right. Nose section & fuselage damaged due to
crash on landing.
Oxy. system hit by flak, hyd system hit by flak. #2
Supercharger hit by flak #3 prop dome hit by flak

AIR	CRAFT AND	T THE	A. D. D. ST.		RD		
ENGINE	NO. 1	NO.	2	NO. B	NO. 4		
HOURS TO DATE	442:20	1/12:	20	142:20	11/12:20		
HOURS	1			9*05			
TOTAL	551:25	453	125	451:25	157:21		
OIL CHANGE			C.		4,		
CUND.CLEAN-			2:2	0			
	HOURS TO DAT	T		442:20	)		
AIRCRAFT	HOURE		9:05				
	TOTAL			451:25	5		

### A TRUE COPY

JOHN N. PAIMER, Capt., Air Corps.


DATE	AIRCRAFT ORG. DATA	AIRCRAFT DATA	ENGINE DATA				
Apr. 25 45	AIR FORCE 8th	COMPONENT	R-1820	<b>-</b> 97			
STATION	Lst	A.A.F.	SW-030188	SW-030167			
106 CHEW CHIEF OR ENGINEER	384	B-17G	SW-030146	SW-030520			
S/Sgt. Mento	544	113-39138	TOTAL PLIGHT TIN				

## RESILLED.

The following is the aircraft accident statement by 1st Lt. Alfred W. Grove, 0-780580, who was Pilot of aircraft #43-39138 on 25 April 1945:

" I was pilot on a/c 43-39138 on today's mission. I was assigned to fly #2 element lead in the Low Squadron. We made a second run on the target and just as we entered the target area the flak became intense and tracking and very accurate. Just after bombs away #3 engine started smoking badly and the cil was pouring out all over the cowling. There was nothing to do but shut off the fuel and feather the engine while it was possible. The #1 turbo was also shot out and the Radio Operator changed the amplifier but the turbo was still inoperative. We could not keep up with the formation and were forced to come home alone. No one on the crew was injured but we had many holes in the plane. After letting down we had three engines because we no longer needed the turbos. Upon reaching 18,000 feet I had the Engineer close the star valve and turned on the hydraulic pump so we could close the cowl flaps. We were still pretty close to enemy soil and I had to use some extra power and so I opened the cowl flaps again to keep the engines from overheating. The hydraulic pressure built up fast and remained normal the entire trip. I let the wheels down over the channel to check them for any damage. Both main and tail gear checked OK visually so I came back to the field for a landing. The hydraulic pressure was OK on the final approach and the engineer called out airspeed and hydraulic pressure upon and after landing. I made a normal landing and when I applied the brakes the left brake held but the right brake had no effect. The fluid leaked out of the right brake line and caused the pressure to drop off completely when brakes were applied. The Co-pilot jumped the hand pump but nothing happened. I advanced the throttles of #1 & #2 but the engines did not take hold quickly enough to avoid hitting another plane which was parked on the left side of the runway.

> ANTRED W. GROVE, lst Lt., Air Corps, Pilot.



# RESTRICTED

Following is a aircraft accident statement by 2nd Lt. Merrill D. Moban, 0-832404, Co-pilot on Aircraft 43-39138 on 25 April 1945.

"On the second run over the target #3 engine was knocked out by flak and we feathered it immediately. The turbo on #1 was knocked out also and couldn't keep with the formation.

Over the channel we let down the wheels and checked the tires and hydraulic pressure. Everything was OK.

Then we got to the field we called for landing information and told the tower we had one engine out. Everything seemed allright, the hydraulic pressure was GK, reading normal. After we landed I called out that hydraulic pressure was GK and the engineer was watching the pressure. When the Pilot started to use brakes, the pressure needle started to flicker and he could not keep the ship straight. The left brake seemed to be holding allright but there was no brake on the right wheel. When the Pilot saw that the brakes were not good, tried to straighten it out with #1 & #2 throttles. They would not take hold and the left tire was in the grass by this time, so nothing to do but try to ground loop. I was trying to get some pressure from the hand pump but it didn't no any good. The ship was in a turn but going so fast that we could not turn fast enough to aboid hitting the other ship.

MERRILL D. HOBAN, 2nd "t., Air Corps, Co-Pilot.

# RESTRICTED

Following is a statement by T/Sgt LeRoy E. Fulmer, ASN 15076562, aerial-engineer, concerning a/c 43-39138 -- accident on 25 April 1945:

"We were hit over the target by quite a few bursts of flak one of which severed the hydraulic line to the right brake. Somewhere off Belgium the pilot told me to close the star-valve, and he operated the

cowa flaps; in that way we knew that we had pressure.

On landing I called the airspeed, and as the wheels hit the runway, I checked and told the piles that the hydraulic pressure was ekay. Then the pilot applied the brakes. As he did, the pressure started to drop off, and the plane pulled to the left and off the runway. He tried to gain control by advancing the throttles on \$1 & 2, but this had no effect. And we crashed into the tail of the plane that was parked on the hardstand. "

> LEROY E. FULMER; T/Sgt., Air corps, Aerial-Engineer.

R-0-1

AAF STATION NO. 106 Office of the Flying Control Officer

26 April, 1945.

SUBJECT: Aircraft Accident Report on B-17 No. 9138.

TO : COMMANDING OFFICER, AAF Station No. 106, APO No. 557, U.S. Army.

- 1. At 1445 hrs on 25 April 1945, B-17 aircraft No. 9138, pilot Grove, returned from operations and was given landing instructions and QFE for runway 24. The aircraft made a normal landing and when approximately two thirds of the way down the runway suddenly ground looped to the left. The aircraft skidded across the grass and collided with another aircraft No. 8013 parked on the inner perimeter near disp. 41. Both aircraft sustained considerable damage.
- 2. Inspection of the runway revealed a heavy skid mark made by the left wheel of the aircraft. This mark continued for quite a distance across the grass.

3. Crash Truck and Ambulance were dispatched. There was no fire damage and no injury to the nembers of the crew.

OMARLES W. OVERTON, 1st Lt., A. C. Duty F. C. O.

APO

55%

1 May, 1945.

SUBJECT: Aircraft Accident Report of B-1/G, #45-39138, 544th Bombardment Squadron, 584th Bombardment Group (H), AAF Station No. 100, APO 55%, 25 April, 1945.

TO : Commanding General, Headquarters, First Air Division, APO 557, U. S. Army.

1. The following report on the above subject is hereby submitted:

FACTS: Aircraft Number 45-59128, 544th Bombardment Squadron, 284th Bombardment Group (H), AAF Station No. 100, APO 557, piloted by 1st Lt. Alred W. Grove, 0-780580, 544th Bombardment Squadron, 284th Bombardment Group (H), AAF Station No. 100, APO 557 was returning from operational mission having sustained considerable battle damage, and in particular to the hydraulic braking system of his aircraft. Upon landing his aircraft, it being unknown to Lt. Grove that his braking system had been damaged, he applied his brakes, and immediately discovered that he had only momentary braking in his left brake, and his right brake was ineffective. The aircraft was swerved to the left, off the runway, starting a ground loop. The left engine was used a little too late in trying to straighten out, and were thus relatively ineffective. The ground loop was almost complete when Lt. GroveRs aircraft struck another aircraft parked about four hundred (400) feet from the landing runway.

FINDINGS: It is the opinion of this officer from the evidence and testimony taken at the meeting of the Accident Board that the underlying cause of this accident was unknown battle damage due to enemy aciton, and that there is no evidence of sabotage to be pursued in this case.

ALEXANDER L. JAMES

1st. Lt., Air orps

Intelligence Officer Member





RESTRICTED















