(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

Just prior to the accident the aircraft in question had had the arms: and armor plate removed, making the tail lighter than on those B-17 aircraft the pilot had been accustomed to flying. The ship made a normal landing on runway 2k, turned right onto the perimeter track and apparently taxing at a slow rate of speed, (5-10 MPH) downwind, when after about 50 yards the right tire blew out. Because of a 15-20 MPH tail wind, slightly from the left of the tail, and the slow rate of taxi, the wind was sufficiently strong in preventing the aircraft from turning appreciably to the right after the blow-out. Ship rolled from 40 to 50 feet, the tail started coming up and the ship nosed over.

According to statements from pilot and engineer no brakes were used in stopping the aircraft. The investigating committee believes that sufficient speed was lost from the deceleration of the aircraft after the tire blow cut to momentarily raise the tail. However, it does seem plausible to the Board that braking action must have been used which of course would materially aid in bringing up the tail. Apparently as soon as the tail started to rise the pilot's immediate reaction was to pull the stick back. Engines had been throttled back while taxing; the wind blowing directly on the raised elevators probably aided in completing the nose over.

The accident could possibly have been avoided if the ship had been dead weighted in the tail while operating under a minimum load condition and during a brisk wind. Possibly if the pilot had realized that his tail had started to rise soon enough and had used an application of power when he pulled the stick back he might have succeeded in forcing the tail back down.

RECOMMENDATIONS: That all ships with armor and armor plate removed be equipped with some dead weight in the tail when the aircraft is being flown under minimum weight conditions. That all pilots be repeatedly cautioned concerning taxing problems with light aircraft.

IMMEDIATE CAUSE: Unknown.

UNDERLYING CAUSE: Blow out of right tire while taxiing. Tail wind aided in nose over after stick was pulled back. The aircraft had armor and armor plate removed moving CG forward. Pilot was not accustomed to new CG althought it was well within the limits prescribed for B-17 operation.

RESPONSIBILITY: Undetermined.

Aircraft Accident Committee:

CLARENCE L. THACKER, Major, Air Corps, Pilot - President.

Mulip Y. William. PHILIP IS WILLIAMS, Major, Air Corps,

Pilot - Member.

JOHN M. PALMER, Captain, Air Corps,

Engineering Officer - Momber.

JACOB R. HALET, Major, Air Corps,

Flying Control Officer (ex-officio).

HITHUR L. POLET

Captain, MC, Flight Surgeon (ex-officio).

alleyander L. James

let Lt., Air Corps,

Intelligence Officer (ex-officio).

(Investigating Officer)

22 My. 19h5.

DATE			GROUP NO. & TYPE					AL	AIRCRAFT MODEL						
16 May 1945 106, England			384 Bomb (H)					1	B-17G						
CREW CHIEF OR AERIAL ENGINEER			545 Bomb (H)					A	AIHCRAFT BERIAL NO.						
M/Sgt Louis Hopps										7986					
ERS.	- PRINT PLAINLY - NAME - ASN GRADE - ORGANIZATION		USE AS DIRECTED	CABLE, ENTER N - NIGHT OR 1 - INS							FLIGHT DATA				
1		2	LOCALLY	DUTY N CR I DUTY N OR I CUTY N OR I		ORIDU	7	ORI	TERMINALS AND	MISSION	9				
18	Welsh, James H., 1st It, 0-1824544		545th	1:	15	<u> </u> -				- <u>‡</u> -		106		07	45
18	Grimm, Karel A., 1st Lt, 0-1639106		545th	OD !	15	<u>!</u>		<u>-</u> -		- <u>:</u> -		106		•9	100
	Reynolds, Edv	ard M., 2nd Lt, 0-836637	545th	30	15			<u>‡</u> -		- <u>!</u> -		MISSION.	NO. OF	01	:1
18	Bernard, Kenr	neth, 2nd Lt, 0-2077696	545th	N_	15	!				<u>-</u> ‡-		FROM			:
38	Rank, Willies	J, Sgt, 17118159	545th	E :		!		<u>!</u> -		<u>-</u>		TO:		-	
38 -	Schwertfeger	Norman H., Sgt, 37740273	545th	G I	15	!				<u>F</u> .		MISSION.	NO. OF	1	3
38	Miller, Lest	or E., Jr, Sgt, 37724170	545th	R	15					- - -		FROM			2-
: 3			1- 7							<u>!</u> .		TO:		1-	المت
	7				<u> </u>		<u> </u>			<u>İ</u>		MISSIONI	NO. OF	5	
- J-	A TRU	E COPY:			ļ		L	ļ!	+	<u>İ</u>		FROM:		T	
.1179	MILL	an S. Sinnaird		 	Ì		ļ	<u>!</u>		<u>i</u>		10,		-	3
	Capt,	Air Corps tions Officer			Ì		<u> </u>	ļ <u>i</u>		<u>i</u>		MISSION:	NO, OF	s	I
					ļ		<u> </u>	ļļ		<u>į</u>		PROMI		1	200
		. 4.			Ì	+	Ì	i		<u>i</u>		70,		7	:
					ţ		İ	‡i		į		MISSION.	NO. C	es.	•
WAR	DEPARTMENT F. FORM NO. 1 (1 JAN. 44)	AIRPLANE FLIGHT REPOR	T - OPERATIO	NS	_	CHECIBI	LE AND	•	W 7	OTAL OTAL	FLIG		TOTA	HT (01:1

Tuck.6

		TE OF	SPECTION		4-4-4	ü	w	ü	EAV				OF TAK				
	н	OR				CE	FUEL (GALLONS)		OIL (QUARTS) NO. 1 NO. 2 NO. 3 NO. 4 SERV. IN SERV. IN SERV. IN SERV.								
PREFLIGHT			HOPPS	106		SERVI	BERY-	T	NO	. 1	NO	. 2	NO	. 3	NO.		
DAILY	7	-	HOPPS	106		8	ICED.	TANKS		IN TANKS	BERV-	IN	SERV-	IN TANKS	SERY-	IN	1
25 HOURS	597						700	1700	1.	140	0	140	0	11.0	0	110	
BO HOURS	622						100	100	-4	140		щ	-	ישע	-0	-140	-
100 HOURS	672					ZHD	-			-							-
IOU HOURS	\vdash	-				RD									_		-
	+	-				STH.											_
	INSPI	CTION	OF AUXIL	ARY EQUIPMENT		_	STATUS	T									
EQUIPMEN		-	LINSPECT	ED BY ST.	ATION -	-	TODAY		XPLAN	ATION	COL	PAS	S WI	NG I	UE:	#1.8	
			1			1.		2.	RIM	REI	BOWS	NO.	, MOL	: FI	UX (ATE	
BOMBARDME	NT					_	_	_ 0	OMPA	SS I	NOP:				140		
GUNNERY						3.		4.			-						_
CHEMICAL	-		-									_				==	_
COMMUNICAT	IONS	L	LONG	BAUGH			WHEN	THE	STATU			AL REL	EASE	BY A	RED S	MBOL.	
PHCTOGRAPH	IC					8	ND A	AUTHO	CEPTIC	MAIN	RELEA	SE" F	FICER.	THE P	EN GR	ANTED	•
NAVIGATION	_					^	IRCRA	FT WI	LL SIG	N THIS	RELE	ASE B	FORE	FLIGH	т.		
	-		-			F		SED FO	R	1-	C.M.	REY	OLD	3			_
						_				12	==	===		4	_		=
REMARKS:	PILO	TS AN	D MECHA	NICS . SEE INST	RUCTIONS INSIDE	FROM	T COVI	LR.		AI			ENGIN			ORD	_
						-				HOME	N	0.1	NO. 2		10. 3	NO.	4
										DATE	18	9125	2555	3	1:45	17	1
				- HOPPS						ODAY	1	1100	4:0	0 1	1100	4:	0
MASTER	IN	DICAT	OR REP	LACED		mente	1			TOTAL	19	9325	295		1845	211	
				4					OIL	CHANGE	1	1	-	+			
	-									O.CLEAN	1	1		+	-		-
				A						o Due		HOURS	T				-
				1							-	HOURS	+	61	4:45		_
									AIA	CRAFT		TODAY	-	- 4	00_		_
												TOTAL		_ 6	1845		
								•									
	25											540					
TRUE CO	PYs	0%	<i>L</i>	Olli										•			
	(THO	KS Y	Mario													
		Cap	te Air	Corps			К		3953.40			W.					
			Engr.														
				100.00							7						
					•	_											
								-									
			AIRCRA	FT DRG. DATA	AIRCRAFT	T D	ATA	T				NGINI	DATA	-			
те		+	AIR FORCE		COMPONENT		-	D	GINE M	ODEL	-	-	-				
TE		1	8TH							R-18	20-0	7					
15/5/45			COMD., SERV. COMD. ON DEP'T		12.1	SERI		RIAL NO	R-1820-97			SERIAL HO.					
15/5/45	_		COMP., SER						~ .	/	•	- 1					- 11
15/5/45					BOMBARDA	TEN	T	"	511-0	3336	9		S	II -02	7765		-
15/5/45 ATTON		L	1ST W	ING	BOMBARDA	EN	r	56	SYI-O	3336	9	-	SERIAL		7765	_	-
15/5/45 ATION 106 EW CHIEF OR E	NGINE		1ST W	ING	The state of the s		<u>r</u>	84	RIAL NO	2368 2368			PERIAL				
15/5/45 ATTON	NGINE		1ST W	ING	The state of the s			-	LAL NO		5		HILL 41	NO.	26	·	

FOLLOWING IS STATEMENT OF THE AIRCRAFT ACCIDENT BY Lat IN JAMES H. WELSH, ASN 0-1824544, ON 16 NAY 1945 IN AIRCRAFT B-17 C # 42-97986

Lended on runway 2-4, turned right on perimeter track and was texting downwind. Wind velocity was approximately twenty (20) miles per hour.

Tail wheel was looked, controls were unlooked, stick was forward and throttles were all the way back. The right tire blow out and no brakes were applied. Plane was rolling fairly straight on perimeter track.

As forward momentum was lost the tail came up and in spite of all efforts pulling the stick back and using throttle, the ship nosed up, damaging nose and No. 2, 3 and 4 props. There were no casualties. I had noticed a definite nose heaviness in this aircraft both in the air and on the ground. I was in the right seat.

JAMES H. WEISH,
lat It., Air Corps
Instructor Pilot
545th Bomb Sq
584th Bomb Gp

RESTRICTED

Suel 21

FOLLOWING IS STATEGOT OF THE ALLEGAT ASSUMPTION LATER AS CRIME ASN 0-1639106, ON 16 NAY 1945, IN AIRCRAFT B-17 G # 42-97906

I was standing behind the seats with the Engineer. The taxi speed was slow and we had a tail wind. The wheel was slightly forward. When the tire blew out the plane nosed up and I did not notice whether the throttles or brakes were used.

I do not think the accident could have been avoided because of the weight removed from the aft part of the plane and also because of the tail wind. I also noticed the lightness of the tail when I flew it the previous day.

EAREL A. GRING, lat Lt., Air Corps Pilot 545th Bomb Sq 384th Bomb Gp

RESTRICTED

Jul3'

FOLLOWING IS STATMENT OF AIRCRAFT ACCIDENT BY 2nd. LT EDWARD M. REYNOLDS ASN 0-836637, ONI6 th. MAY 1945, IN B-17 G, AIRCRAFT # 42-97986

1. Landed on runway 2-4-0 and made right hand turn onto the perimeter track. Had gone a short distance with the wind to our back, when the right tire blew. I had about 600 R.P.M. on the inboards and about the same on the outboards. I did not apply any brake, and had gone only a short distance when the tail came up. I pulled back on the stick and added some throttle to try and get it back down. The extent of the damage was #2,3 and 4 props being. ruined and the nose badly damaged, I was in the left seat.

2. There were no personnel injured.

ENWARD M. REYNOLDS, 2nd. LT. AIR CORPS,

PILOT, 545th BOMB SQUADRON 384th. BOMB GROUP

heunard ED

R-0-1

Office of the Flying Control Officer

16 May. 1945.

SUBJECT: Aircraft Accident.

TO : COMMANDING OFFICER, AAF Station No. 106, APO 557, U. S. Army.

- 1. At approximately 0850 hours B-17 No. 7986, pilot Welsh, was taxying on the perimeter track near dispersal 46 after having made a landing on runway 24. The right tire blew out and the aircraft nosed over on the perimeter, driving the chin turret up into the mose and damaging No. 2,5, and 4 props.
- 2. Operations, Eagineering and Photo Lab were informed immediately. Ambulance and crash tender were dispatched from the Control Tower. No one was injured and there was no damage to the airfield or property other than the aircraft itself.

Charles W. OVERTON,
1 st Lt., A. C.
F. C. O.

KESTILLIED

Such 5'

KEUTING. ED

HEADQUARTERS

AAF STATION NO. 106
Office of the Intelligence Officer

D-7-6

23 May 1945, APO 557.

SUBJECT: Intelligence Officers Report on Aircraft Accident Involving Aircraft B-17-6 Humber 42-97956, 16 May 1945.

- 10 . Commanding General, Readquarters, let Air Division, APO 557, We Army.
 - 1. The following report covering subject is hereby submitted.

PACTS: Aircraft Number 42-97966 pileted by 1st Lt. James H. Welsh, 0-828474, 545th Bomb Squadron, 384th Bomb Group, Station 106, APO 557, was taxing at a slow rate of speed downwind when the right tire blow out. There was a 15 - 20 M.P.H. tail wind. The plane continued to taxi 40 - 50 feet when the tail started to come up and the plane need over. The plane recently had all armor plate removed.

PINDINGS: From all the facts presented there is no evidence of sabotage to be pursued in this case.

Alexander Landa Alexandra Land

KEDIMU ED

Inal 8

HRADQUARTERS AAF STATION NO. 106 Office of the Station Commander


23 My, 1945.

SUBJECT: Letter of Transmittal.

: Commanding General, 1st Air Division, APO 557.

Transmitted herewith is AAF Form 14 and allied papers on aircraft B-17G 42-97986, which was involved in an accident on 16 May 1945.

For the Station Commander:



9 Incls:

Incl 1 AAF Form 14 (in quad).

Incl 2 Instructor Pilots Statement (in quad).

Pilots Statement (in quad).

Incl 4 Co-pilots Statement (in quad).

Incl 5 Flying Control Officers Statement (in quad).

Incl 6 AAF Form 1 (in quad)1

Incl 7 AAF Form 14 (in quad).

Incl 8 Intelligence Officers Statement (in quad)

Incl 9 Photographs (2 sets, 4 prints ea)

HEADQUARTERS 1ST AIR DIVISION, APO 557, 26 May 1945.

(E/R/8)

To: Commanding General, Eighth Air Force, AAF Station 101, APO 634.

Perwarded in compliance with Paragraph 1, Section V, Righth Air Ferce Memorandum 60-1, dated 27 March 1944.

FOR THE COMMANDING CENER

Major, AGD

(in trip)

360.33 lst W/Ind. Hq. Eighth Air Force, APO 634, % Postmaster, New York.

JUN 1 1946

To: Chief, Flying Safety, AAF, Winston-Salem 1, N.C.

- 1. Transmitted herewith WD AAF Form No. 14 and allied papers on the following aircraft accident:
 - a. 1st Lt. James H. Welsh, B-17G number 42-97986.
- 2. This headquarters does not concur in assessment as 100% undetermired. It is felt that a better assessment would be 100% miscellaneous, further subdivided as 30% materiel failure, tire; 30% weather; 40% c.g. factor. The general heading of miscellaneous is given because no single one of these factors would have caused this accident; only the combination that existed at this particular moment could have resulted in this specific accident.

FOR THE COMMANDING GENERAL:

HENE ARCHIR

ME AL CO

1 Incl: as above.