	1	
WAR	DEPAR	MENT IN NO. 14
A. A.	P. POST	E No. 16
(Revi	md With	16, 1962)

REPORT OF AIRCRAFT ACCIDENT (1) Place 42 miles south of Kettering (malgrave) 2) Date 6 April 1945 AIRCRAFT: (6) Type and model B-170 (6) A. E. A. E. A. L. (6) Station AAF Station 106 Organization: (7) Bth (Sommand and Air Force) (8) 36lith Bomb (H) (8) 5li5th Bomb (H) (South Command and Air Force) PERSONNEL NAME (Last name first) PERSONNEL CLASS AIR FORCE OF CONNAND RESULT TO USE OF SERIAL NO. RANK BRANCE Dutt (14) (18) (19) (10) (11) (19) (13) (16) (17) 0-828474 lat Lt. 8th Nil MacKeller, Donald A F/0 McLaughlin, Orland F. T-7789 18 0=2068605 2nd Lt. Cebulski, Leo C. N. Sammels, Robert H. 13151,055 S/Set. 38 3753716 Fruitt, David L. 38 Connell, Harvey Ca 36811845 S/Set. 38 13172510 Courtney, Raymond F. S/Set. 38 8th Bronsetti, Marren J. 1206 12060052 Y AUTHORITY OF CG A A (22) let Lta (23) Assigned (35) ... Attached for flying (29) Apriluly resent rating (25) Pilot. (36) 15 Original rating (33) Pilot Apr allunstrument rating (37) 17 Oct all FIRST PILOT HOURS: (at the time of this accident) (38) This type.... (42) Instrument time last 6 months. 128:20 (43) Instrument time last 30 days. (39) This model. (40) Last 90 days (44) Night time last 6 months. (41) Total.... (45) Night time last 30 days AIRCRAFT DAMAGE DAMAGE (49) LIST OF DAMAGED PARTS (46) Aircraft. Complete Destruction (47) Engine(s)... (48) Propeller(s). (59) Weather at the time of accident No clouds, visibility 3 miles, wind Why 9 MPH (51) Was the pilot flying on instruments at the time of accident . (52) Cleared from AAF Station 106 (53) To Operational (54) Kind of clearance . Operational (55) Pilot's mission Miscellaneous - A/C crashed after catching fire in the air at low altitude. Inderlying causes foldown. Believed to be Cause of accident ... loss of power of two engines.

(SR) Was Form Su been submitted? Hoe

DESCRIPTION OF ACCIDENT

(Brief narrative of accident. Include statement of responsibility and recommendations for action to prevent repetition)

The A/C took off from base in the early morning darkness on an operational mission to the Continent. After take-off a turn south was made to the first con course heading. Trouble apparently started about three or four minutes out, as the A/C was seen from the base tower, and from anoth airbourne A/C, to be losing altitude in a right turn. After turning approximately 150° the A/C crashed into a road about him miles SW of Kettering. The A/C blew up and several of the bombs followed exploding at frequent intervals. Wreckage was scattered over an area nearly mile radius from the crash.

Investigation following the accident disclosed that: 1. The crew had been alerted to bail out too late for any one to escape, as the escape hatches were found about 500 yards from the scene of the crash; 2. Fire had started in the air a few minutes prior to the crash; 3. The two right hand engines (#3 & 4) were not developing as much power as No's. 1 & 2 when the crash occurred; 4. The A/C struck the ground in a shallow dive apparently out of control. The underlying causes have been undetermined beyond mere speculation.

Responsibility: None charged due to the nature of the accident and the absence of definite cause, it has been impossible to fix any responsibility.

Recommendations: None.

MAY 1 1945

ALEI C. STRICKIAND,

Major, Air Corps,

Squadron Commander.

T. D. HUTCHINSON, Major, Air Corps, Operations Officer.

MICOIAI (NMI) HANSEN, Wajor, Air Corps, S-4 Officer.

Signature _____

Deta 16 April. 1915.

Ng 505 USAFP18-43/25W/13350.

6 April 1945 station 106			384th (H) Bomb							B-17G					
CREW CHIEF OR AERIAL ENGINEER S/Sgt Alfred Mariani		SQUADRON	SQUADRON No. & TYPE							AIRCRAFT SERIAL No.					
		545th (H) Bomb						44-6923							
PERS.	NAME	USE AS DIRECTED LOCALLY	ALWAYS ENTER DUTY SYMBOLS, W. CABLE, ENTER N-NIGHT OR I-INS						APPLI- MENT.	FLIG	A				
1			LOCALLY						PM	7 NORI	TERMINALS AND MIRRIGH		•		
18	MacKellar, D.	A., let Lt, 0-826474	545	P					+	<u>-</u>	PROM:		04 : 2		
17	McLaughlin, O	545	CP					+	<u>_</u>	TOI	;				
18	Cebulski, L.	545	N		<u> </u> -			-		MISSION		:			
38	Samuels, R. H	545	TOG	ļ	Į.		<u> </u>	+		FROM	1:				
38	Connell, H. C	., s/sgt, 36811845	545	E	ļ	1			-	-	TO1		1 g : [
38	Fruitt, D. L.	545	R	ļ	I.			-	1	MISSION					
38	Courtney, R.	545	LB					-		PROMI	. 3				
38	Bronzetti, W.	Bronzetti, W. J., S/Sgt, 42060052		TG	ļ				+		TO1				
	al a			-	Ì	1			-	<u> </u>	MIBBIONI	Lastrate	1:		
				-	<u> </u>			1	-	Ļ			:		
				-	į			<u> </u>	-	Ļ	TO:		:		
	A TRUE COPY: JOSEPH S LABODA Capt, Air Corps Operations Officer			-	<u> </u>			l i		i_	MISSIONI	1.55.55			
				-	į						PROMI		7:		
					Ì.			1			Y01	*	1:		
		mb Sq, 384 Bomb Gp		-	İ			1				T.	- :		
WAR D	PARTMENT FORM No. 1	AIRPLANE FLIGHT REPO	RT - OPERATI	ONS		CHEC	LE AN	1	M	TRANSO	RIBED:	TOT	Hr		

WAR DEPARTMENT

AIRPLANE FLIGHT REPORT - ENGINEERING

	11	SPECTION S	TATUS	200	1.							OF TA			3			
DATE OF INSPECTED TO			DAY.	FOEL			OIL E											
	PUE	ey	· 87A	TION	SERVICE	IGAL					-(90	ARTE	RTBI			RADIATOR		
PREFLIGHT	6-4-45	V	106		E R	SERV. IN		NO. 1		NO. 2				-	. 4	V		
DAILY -	6-4-45	M	106	1	. O ICED TAN		TANKS	SERV-	TANKS	SERV.	TANK	SERV-	TANK	SERV-	TANKS			
28 HOURS	349:45			٨	167		2500		140		140	-	110		140	:		
50 HOURS	374:45				2ND													
100 HOURS	421:45				380										4.			
123.110.1112	4-2142				4TH		-		-									
					5TH					-						-		
	NEPECTION	OF AUXILIA	RY EQUIPMEN	т	1	TATUS	T	-		ca	ma e	0 0167	NO 1	ALD				
EQUIPMENT	-	L INSPECTED	BY .	TATION	-	TODAY	-	EXPLANATION COMPASS SWING DUE										
BOMBARDMEN'					1			NAV. AIRSPEED NEEDS CAL.										
	-				1	+	-								121100001			
GUNNERY					*													
CHEMICAL	-	OI ITOOMIT	m 30/	,									=			=		
COMMUNICATIO		CHESTN	UT 106		,	VHEN	THE "	STATU	B TODA	Y" IS	INDI	CATED	BY A	RED S	YMBOL			
PHCTOGRAPHIC						ND A	N +EX	RITED	MAIN	RELEA	SE OF	FICER.	THE	EN GI	PANTED	2		
NAVIGATION C		HUGERIO			^	IRCRA	FT WIL	L SIG				EFORE		т.				
_ 0 ₂		MARIAN	106		F	ELEAS	ED FO	R	1.D	A.V	AC_X	KLIA	B			_		
					-		911		12_	_			4		_	_		
REMARKS P	LOTS AN	D MECHAN	ICS . SEE INS	TRUCTIONS INSIDE	FROM	r cove	A .		AI	RCRAF	T AND	ENG!	NE TIM	E REC	ORD			
									HGINE	N	0. 1	NO. I		HO. 3	NO.			
									O DATE	34	7:10	347:1	0	5612	347	10		
									HOURS	-								
									TOTAL				T					
									CHANGE	1,21	11.4	2414	5 10	3120	h2h s	45		
								CUM	o.CLAN	-			-	_	-	~		
								-	O DUE		HOURS	T		-		-		
								ATRICRAFT HOURS TODAY					_					
H. J. & 1979 Special Contract							-											
***	A T	RUE COPY						-		-			_	_		7		
			•	00			-	-			-	-	-	-		-		
			7.19	()()			-				NAME OF TAXABLE		-			-1		
		-	THOMAS P.		nu	,				-		-		_	-	-		
				Air Corps							-					-1		
	Contractor of the Contractor o			ineering		^ar			-		-		_	_		-		
			an Arth with	THANK THE	****	out ,	-			-			-			\dashv		
								-					-			4		
						-						-				4		
							-											
·c					-	_	_		_					*				
6-4-45	-	AIRCRAFT	DRG. DATA	AIRCRAF	T DA	TA					NGINE	DATA	,					
-44)	1	AIR FORCE	IIIth	COMPONENT			ENG	R-1820-97								1		
TION	1	OND., SERV. O	OHO. OR DEP'T	BOMBARDM	ENT		SER.	IAL NO.					W0			4		
106	1	Lat WING						-036169		1000			AL NO.			1		
		ROUP NO. & TO		AIRCRAFT NODEL	-			MIAL NO.					336	т_	-	1		
W CHIEF OR ENG!	MEER	384tb (H		B-170	-	*****	SI	-019038				SW-033356						
								TAL FLIGHT TIME					73330					
Sgt. WARL	ANI.	Susta (H		Marchart SERIAL		1								-	-	1		

HEADQUARTERS

AAF STATION NO. 106
Office of the Intelligence Officer

D-J-3

APO 557

16 April, 1945.

SUBJECT: Aircraft Accident Report of B-17-G, #44-6923, 545th Bombardment Squadron, 384th Bombardment Group (H), AAF Station No. 106, APO 557, 6 April, 1945.

TO : Commanding General, Headquarters, First Air Division, APO 557, U. S. Army.

L. The following report on the above subject is hereby submitted:

FACTS: Aircraft Number hh-6923, Sh5th Bombardment Squadron, 384th Bombardment Group (H), AAF Station No. 106, APO 557, piloted by 1st Lt. Donald A MacKeller, 0-828474, 545th Bombardment Squadron, 384th Bombardment Group (H), AAF Station No. 106, APO 557, had just taken off from this field for an eperational mission. The aircraft was seen to be losing altitude three (3) or four (4) minutes out, both by the tower and another airborne airdraft, during a right turn. The aircraft turned approximately 150 degrees and then crashed into a road about four and one half ($\frac{1}{4}$) miles SW of Kettering. The aircraft blew up and several of its bombs exploded at frequent intervals, causing wreckage to be scattered over an area of nearly one half ($\frac{1}{4}$) mile radius. All members of the crew were killed.

FINDINGS: It is the opinion of this officer from the evidence found at the scene of the crash by the investigating officer, Major Phillip I. Williams, that fire had started in the aircraft a few minutes prior to the crash, that the two (2) right hand engines (#3 and #4) were developing as much powers as were No.'s 1 and 2 when the crash occured, and that the aircraft struck the ground in a shallow dive apparently out of control, and that the definite cause of the accident is indeterminable. From the evidence and findings there is no evidence of asbotage to be pursued in this case.

ALEXANDER L. JANES, lst Lt., Air Corps, Intelligence Officer Member.

SECRET

4

SECKE

The following is a statement by F/O ALFRED D. HFSKO, T-132935, on aircraft accident.

We followed aircraft #hh-6923 down the runway and in the climb I was watching what we believed to be his signal lamp in the tail. It descended gradually until we saw a big explosion and after that we realized that the light we followed was too big to be his signal lamp, but in all probability some part of the aircraft was on fire. Didn't circle the scene of the accident for fear of exploding bombs.

ALFRED D. HESKO, F/O, Air Corps,

)

SECKET

SECRET

MEADQUARTERS

AAF STATION NO. 106

Office of the Flying Control Officer

H-D-1

14 April, 1945.

SUBJECT: Aircraft Accident of A/C No. 6923.

TO : COMMANDING OFFICER, AAF Station No. 106, APO No. 557, U. S. Army.


1. On 6 April, 1945 at 0455 hours aircraft No. 6923 pilot Lt. McKeller was airbourne on operational mission.

2. At approximately 0500 hours I saw an aircraft with an aldis lanp flashing in the tail losing altitude and turning to the right of the QDM of the runway 24, several miles from the field. The light disappeared and a dull flash followed by several bright flashes then occurred.

3. An airbourne aircraft from this station gave the approximate location of a crash as southwest of Kettering.

4. Orash Tender and Ambulance were dispatched immediately. All concerned were notified.

JAMES N. BILLS, 1st Lt., A. C., Duty F. C. O.



SECRET

Author G. Stor A.F. Init. APR 1945

360.33 lst Wrapper Ind. 24 APR 194 Hq, Highth Air Force, APO 634, o/o Postmaster, New York, N.Y.

rk, N.Y.

TO: Chief, Flying Safety, AAF, Winston-Salem 1, N.C.

1. Transmitted herewith WD AAP Forms No. 14 and allied papers on the following aircraft accidents:-

4

a. 2nd Lt. Theodore G. Jordon, B-17G number 44-6109. b. lat Lt. Bonald A. MacKeller, B-17G number 44-6923.

2. Concur.

FOR THE COMMANDING GENERAL

BURNIS ARCHER

Major, A.G.D.,
Asst. Adjutant General.

2 Inclas

As shove.

SECRET

20-74506

319.1 0/8.

1st Ind.

G-G-8

HEADQUARTERS EIGHTH AIR FORCE, AAF STATION 101, APO 634, US Army. JUN 11 1945

TO: Commanding General, 1st Air Division, APO 557, US Army.

For compliance with basic communication and return through this headquarters.

BY COMMAND OF MAJOR GENERAL KEPMER:

H. S. WILSON, OR .. Major. A.G.D.,

Asst. Adj. Gen.

HQ. 1st AIR DIV BASIC: Ltr, Hq. AAF, Wash, DC, June 45, Subj: F/O Orland F. McLaughlin, T-007789, 545 BS, 384 BG, APO 557, NY, KIA 6 Apr 45.

312.1 2nd Ind. HEADQUARTERS, 1ST AIR DIVISION, APO 557, 13 June 1945.

(G/D/19)

TO: Commanding Officer, 40th Combat Wing, APO 557.

For compliance with basic communication and return through this headquarters.

BY COMMAND OF BRIGADIER GENERAL BEAMAN:

CHARLES E. GARVIN,

Capt., Air Corps, Actg. Asst. Adj. Gen.

BASIC: F/O O.F. McLenghlin, T-007789, 384th BG, killed in action 6 Apr 45, dtd 2 Jun 45. HEADQUARTERS 40TH CONBAT BOND WING (Hw), APO 557, 14 JUNE 1945.

TO: Commanding Officer, 384th Bomb Group (Hv), APO 557. U. S. Army.

For compliance with basic communication and return through this Headquarters.

BY ORDER OF COLONEL MUSTOR:

lst. Lt., A.C., Adjutant.

CONFIDENTIAL

4th Ind.

(C-A-18)

HEADQUARTERS, AAF STATION NO. 106, APO 557, 16 June 1945.

TO: Commanding Officer, 40th Combat Bomb Wing (H), APO 557.

- 1. F/O Orland F. McLaughlin, T-7789, was Killed in Action near Kettering, England, 6 April 1945, while serving as Co-Filot of B-17 aircraft #WW-6923
- 2. A/C #44-6923 crashed in the early morning darkness almost immediately after take-off for an operational mission over Germany. Entire crew was killed. No further information is available.
 - 3. Complete crew list is as follows:

ist Lt.	Donald A. MacKellar	0-828474
F/0	Orland F. McLaughlin	T-7789
2nd Lt.	Leo C. Cebulski	0-2068605
S/Sgt.	Robert H. Samuels	13154055
Sgt.	David L. Fruit -	37537164
s/sgt.	Harvey C. Connell ~	36811845
S/Sgt.	Raymond F. Courtney	13172510
S/Sgt.	Warren J. Bronzatti	42060052

For the Station Commander:

J. R. Wyatt, Capt., Air Corps, Adjutant.

BASIC: P/O O.F. McLaughlin, T-007789, 384th BG, killed in action 6 Apr 45. 2 Jun 45. 319.1 5th Ind. 6.A.4 HEADQUARTERS 40TH BOMB WING (H), APO 557, 19 JUNE 1945.

TO; Commanding General, 1st Air Division, APO 557. U. S. Army.

Attention is invited to preceding indersement.

FOR THE COMMANDING OFFICER:

NORMAN P. SPICER, 1st. Lt., A.C., Adjutant.

ONFIDENTIAL

BASIC: Ltr, Hq. AAF, Wash, DC, 2 June 45, subj: F/O Orland F. McLaughlin, T-007789, 545 BS, 384 BG, APO 557, NY, KIA 6 Apr 45. (G/D/19)312.1 6th Ind. HEADQUARTERS, 1ST AIR DIVISION, APO 557, 22 June 1945. TO: Commanding General, Eighth Air Force, AAF Station 101, APO 634. Attention is invited to 4th Indorsement. FOR THE COMMANDING GENERAL: CHARLES E. GARVIN. Capt., Air Corps, Actg. Asst. Adj. Gen. 319.1 8/5 G-G-8 7th Ind. HEADQUARTERS EIGHTH AIR FORCE, AAF STATION 101, APO 634, US Army. JUN 24 1945 TO: Commanding General, European Theater of Operations, APO 887, US Army. (Attn: AG Casualty Section) Attention invited to 4th indorgament. FOR THE COMMANDING GENERAL, 18 H.S. WILSON, JR., Major, A.G.D., Asst. Adj. Gen, 8th Ind. 319 HQ. U. S. FORCES, EUROPEAN THEATER (REAR), APO 887, U S Army. 3 July 1945 TO: Commanding General, Army Air Forces, Washington 25, D. C. Records this headquarters indicate status of subject officer as KIA 6 April 1945. FOR THE THEATER COMMANDER: by E. A. BRADUNAS, Lt. Col., AC H. M. RUND. My by F. M. MUENCH, Capt., AC Colonel, AGD Dete FEB 25.1946. Asst.Adj.Gen.

CONFIDENTIAL.

319.1 0/9

#

7th Ind.

G-G-8

HEADQUARTERS EIGHTH AIR FORCE, AAF STATION 101, APO 634, US Army.

TO: Commanding General, European Theater of Operations, APO 887, UN 19 1945
US Army. (Attn: AG Casualty Division)

1 JUN. 1945

Information requested in basic communication is contained in 3rd, 4th and 5th Indorsements.

FOR THE COMMANDAME SEMERAL:

AL S. WILSON, JR.,

Major. A.G.D.,

1 Incl: n/c.

CONFIDENTIAL

to RESTRICTED
by E. A BA Lt: col., At by F. M. MOEN. B. apt. A.

Pate FEB 25 1946

AG 704 Cas

8th Ind.

GFF/1b

HEADQUARTERS EUROPEAN THEATER OF OPERATIONS, APO 887, U. S. ARMY, 22 June 1945

TO: Commanding General, Army Air Force, Washington 25, D.C.

Vincle n/c

V. J. H.

RA-8

CONFIDENTIAL

1st Lt. Denald A. MacKellar

2nd Lt. Leo C. Cebulski

F/O Orland F. McLaughlin

S/Sgt. Warren J. Bronzetti

S/Sgt. Raymond F. Courtney

S/Sgt. Harvey C. Connell

S/Sgt. Robert H. Samuels

Sgt. David L. Fruit

Mrs. Margaret MacKellar (mother) 1833 North Berendo Hollywood, California

Mr. Tony J. Cebulski (father) 410 Stone Street Georgetown, Illinois

Mrs. P. E. McLanghlin (mother) Medway, Maine

Mrs. Genma Bronsetti (mother) 645 Marcy Avenue Brooklyn, New York

Mr. Charles J. Courtney (father) R. F. D. Number One Atlantic, Pennsylvania

Mrs. Mary B. Connell (mother) 2. 0. Box Number Sixteen Genesee Depot, Wisconsin

Mrs. Grace B. Samuels (mother) 1823 Dallas Street Philadelphia, Pennsylvania

Mrs. Deris K. Fruit (mother) 2508 Maryland Topeka, Kansas



